KIT INSTRUCTIONS

Wall Mount

7702-K320

Issue D

Revision Record

Issue	Date	Remarks
A	Jun 2014	First Issue
B	Feb 2017	Added screws for XL15 Display
C	July 2017	Added XL10 Display
D	June 2018	Added X-Series Displays (5968/5985)

Wall Mount

This kit provides components to secure any of the following to a vertical surface:

- RealPOS XR5 POS (7701)
- RealPOS XR7 POS (7702)
- RealPOS XR7 Plus POS (7703)
- X-Series Displays (5968/5985)
- XL10 Display (5910)
- XL15 Display (5915)

Kit Contents

Wall Mount Bracket
497-0502979

Screw, M4 x 8, Machine
Phillips, Pan Head
006-8615964

Screw, M4 x 12,
Phillips, Pan Head
006-8622686

VESA Mount
497-0502264

33325

Installation Procedures

1. Secure the VESA Mount (with UP arrow pointing up) to the vertical surface using lag screws (4). Make sure you install the screws into the studs or that you use hardware of similar strength. Use the bracket as a template to mark the location of the holes or use the dimensions shown below.

⇧ UP

174 mm
(6.9 in.)

130 mm
(5.1 in.)

⇩ DOWN

120 mm
(4.7 in.)

140 mm
(5.5 in.)

33327

2. Install the Wall Mount Bracket (with the thumb screw facing up) onto the back of the terminal with the supplied screws (4). Use the appropriate screws for the terminal.

Terminal	Screw
RealPOS XR5 (7701) RealPOS XR7 (7702) Real POS XR7 Plus POS (7703) X-Series Displays (5968/5985)	006-8615964 M4 x 8, Machine, Phillips, Pan Head
XL10 Display (5910) XL15 Display (5915)	006-8622686 M4 x 12, Machine, Phillips, Pan Head

33326

3. Hang the terminal on the VESA Mount.

   a. Insert the mushroom studs on the Wall Mount into the elongated slots on the VESA Mount.

   b. Slide the terminal down to lock the brackets together.

   c. Secure the brackets with the thumbscrew.

Thumbscrew

Wall Side of Bracket

33328